



Tools:

Tool Chest (no larger than 12"x 12" x 24")
Test Indicator (Starrett or equivalent quality)
Hex key set (Allen wrenches) – standard and metric
Adjustable wrench
Center gage (60°)
6" Steel machinist rule
Micrometer 0-1" – (Starrett or equivalent quality)
6" Caliper – digital or dial (Starrett or equivalent quality)
Edge finder - .200 diameter
Deburring tool
Parallel Set

PPE (Personal Protection Equipment):

Safety glasses with side shields
Safety-toed work shoes or boots

Recommendations:

- Do not wear loose fitting clothing that may get caught in machine; shorts sleeves or tightly rolled up sleeves recommended.
- Long hair should be pulled back and securely fastened
- Shop aprons should be worn to reduce wear and tear on clothing